

E1

-
- The diagram shows a continuous beam with three spans. The left end is a fixed support (1). The first span has a uniformly distributed load (2) and a point load (3) at its midpoint. The second span has a fixed support (4) at its left end and a roller support (5) at its right end. The third span has a roller support (6) at its left end and a fixed support (7) at its right end. A uniformly distributed load (8) is applied to the third span. The beam is symmetrical about a vertical dashed line in the center, with corresponding components labeled on both sides.



CAÑERÍA EXISTENTE
CAÑERÍA A INSTALAR

RAVAL SIMPLE



PUNTO MED. DE PRESIÓN

Comitente/Costeante	Beneficiario	Valor	Observaciones

ING. DANIEL HERRERA
Dirección General Unidad
Ejecutora Agua Potable
Mesa de trabajo: Desastres en Ciénagas de

PLACENTALIDAD DE CORDOBA
Nombre y Apellido: Justo Daniel Herrera
Director Gen. Unidad Ejecutora a Carga Poble
DNI Nr.: 15.013.902 Teléfono: 351 4.285.660 h/f - 1800
Direccion: Av. Marcialo T. de Alvear 120 - 5to. Piso

PLANO DE :
PROYECTO

OBRA DE RED DISTRIBUIDORA AGUA DE VILLA EL LIBERTADOR
(ASENTAMIENTO LAS TABLAS)

Plano N°: 1